



COLORADO
Division of Water Resources
Department of Natural Resources
Dam Safety Branch

August 15, 2024

Mr. Scott Southworth
Falls Creek Ranch Association
6530 Falls Creek Main
Durango, CO 81301
via email: scottrobin410@gmail.com

When replying, please refer to:
TURNER DAM, DAMID 300113
Water Division 7, Water District 30

SUBJECT: 2024 Engineers Inspection Report

Dear Scott,

On July 26, 2024, I performed a dam safety inspection for the above referenced structure in accordance with Section 37-87-107, C.R.S. (1991 Repl. Vol.), which assigns the responsibility for the determination of the safe storage level for the reservoirs within Colorado to the State Engineer. The enclosed inspection report summarizes my findings during the inspection.

The condition of the Dam is rated as Satisfactory, and the recommended safe storage level is Full Storage. Please read the report and implement the recommendations on page 3.

If you have any questions, please contact me at 970-317-4147.

Sincerely,

Matthew J Gavin, P.E.
Colorado Dam Safety Branch

ec: Rob Genualdi, Division Engineer, Water Division 7
John Batka, Chief, Dam Safety Branch
Jeff Titus, Water Commissioner, WD30



ENGINEER'S INSPECTION REPORT

INSPECTOR: MJG

OFFICE OF THE STATE ENGINEER - DIVISION OF WATER RESOURCES - DAM SAFETY BRANCH

1313 SHERMAN STREET, ROOM 818, DENVER, CO 80203, (303) 866-3581

DAM NAME: TURNER T: 360N R: 0090W S: 21 COUNTY: LA PLATA DATE OF INSPECTION: 7/26/2024
DAM ID: 300113 YRComp: 1969 DAM HEIGHT(FT): 35.0 SPILLWAY WIDTH(FT): 125.0 PREVIOUS INSPECTION: 9/28/2023
CLASS: High hazard DAM LENGTH(FT): 510.0 SPILLWAY CAPACITY(CFS): 5000.0 NORMAL STORAGE (AF): 472.0
DIV: 7 WD: 30 CRESTWIDTH(FT): 22.0 FREEBOARD (FT): 6.0 SURFACE AREA(AC): 42.0
EAP: 10/1/2022 CRESTELEV(FT): 7150.0 DRAINAGE AREA (AC.): 4057.0 OUTLET INSPECTED: 8/23/2013

CURRENT RESTRICTION: -- NONE --

OWNER: FALLS CREEK RANCH ASSOCIATION, INC. (SOUTHW OWNER REP.: SCOTT SOUTHWORTH
ADDRESS: 6350 FALLS CREEK MAIN CONTACT NAME: SCOTT SOUTHWORTH
DURANGO CO 81301-0000 CONTACT PHONE: (970) 247-9506X

INSPECTION PARTY: Scott Southworth Bill Chambers
REPRESENTING: FCRA FCRA

FIELD CONDITIONS OBSERVED	WATER LEVEL: BELOW DAM CREST ~6.3 FT. <u>Below</u> Spillway ~0.35 FT. GAGE ROD READING N/A
	GROUND MOISTURE CONDITION: <input checked="" type="checkbox"/> DRY <input type="checkbox"/> WET <input type="checkbox"/> SNOWCOVER OTHER

DIRECTIONS: MARK AN X FOR CONDITIONS FOUND AND UNDERLINE WORDS THAT APPLY

UPSTREAM SLOPE

- PROBLEMS NOTED (0) NONE (1) RIPRAP - MISSING, SPARSE, DISPLACED, WEATHERED (2) WAVE EROSION - WITH SCARPS
 (3) CRACKS WITH DISPLACEMENT (4) SINKHOLE (5) APPEARS TOO STEEP (6) DEPRESSION OR BULGES (7) SLIDES
 (8) CONCRETE FACING - HOLES CRACKS, DISPLACED, UNDERMINED (9) OTHER

No changes or concerns noted.

CONDITIONS OBSERVED: Good Acceptable Poor

CREST

- PROBLEMS NOTED (10) NONE (11) RUTS OR PUDDLES (12) EROSION (13) CRACKS - WITH DISPLACEMENT (14) SINKHOLES
 (15) NOT WIDE ENOUGH (16) LOW AREA (17) MISALIGNMENT (18) IMPROPER SURFACE DRAINAGE (19) OTHER

No changes or concerns noted.

CONDITIONS OBSERVED: Good Acceptable Poor

DOWNSTREAM SLOPE

- PROBLEMS NOTED (20) NONE (21) LIVESTOCK DAMAGE (22) EROSION OR GULLIES (23) CRACKS - WITH DISPLACEMENT (24) SINKHOLE
 (25) APPEARS TOO STEEP (26) DEPRESSION OR BULGES (27) SLIDE (28) SOFT AREAS (29) OTHER

Vegetative cover appears slightly improved this year. No concerning erosion noted.

CONDITIONS OBSERVED: Good Acceptable Poor

SEEPAGE

- PROBLEMS NOTED (30) NONE (31) SATURATED EMBANKMENT AREA (32) SEEPAGE EXITS ON EMBANKMENT
 (33) SEEPAGE EXITS AT POINT SOURCE (34) SEEPAGE AREA AT TOE (35) FLOW ADJACENT TO OUTLET (36) SEEPAGE INCREASED / MUDDY
DRAIN OUTFALLS SEEN No Yes Show location of drains on sketch and indicate (37) FLOW INCREASED / MUDD (38) DRAIN DRY / OBSTRUCTED
 (39) OTHER

Seepage control is very good. No signs of seepage; no hydrophytes in toe area.

CONDITIONS OBSERVED: Good Acceptable Poor

OUTLET

- PROBLEMS NOTED (40) NONE (41) NO OUTLET FOUND (42) POOR OPERATING ACCESS (43) INOPERABLE
 (44) UPSTREAM OR DOWNSTREAM STRUCTURE DETERIORATED (45) OUTLET OPERATED DURING INSPECTION YES NO
INTERIOR INSPECTED (120) NO (121) YES (46) CONDUIT DETERIORATED OR COLLAPSED (47) JOINTS DISPLACED (48) VALVE LEAKAGE
 (49) OTHER

Gate was exercised with no problems encountered. (48) Leakage is always an issue following gate operation; however, this does not present any immediate dam safety concerns.

CONDITIONS OBSERVED: Good Acceptable Poor

SPILLWAY

- PROBLEMS NOTED** (50) NONE (51) NO EMERGENCY SPILLWAY FOUND (52) EROSION WITH BACKCUTTING (53) CRACK - WITH DISPLACEMENT
 (54) APPEARS TO BE STRUCTURALLY INADEQUATE (55) APPEARS TOO SMALL (56) INADEQUATE FREEBOARD (57) FLOW OBSTRUCTED
 (58) CONCRETE DETERIORATED / UNDERMINED (59) OTHER

Spillway has good geometry and is maintained free of obstructions. The channel was recently mowed prior to the inspection and has the appearance of a city park.

CONDITIONS OBSERVED: Good Acceptable Poor

MONITORING

- EXISTING INSTRUMENTATION FOUND (110) NONE (111) GAGE ROD (112) PIEZOMETERS (113) SEEPAGE WEIRS / FLUMES
 (114) SURVEY MONUMENTS (115) OTHER
 MONITORING OF INSTRUMENTATION (116) NO (117) YES PERIODIC INSPECTIONS BY: (118) OWNER (119) ENGINEER

Dam has suitable monitoring for operational needs. (118) Residents recreate frequently on and around dam.

CONDITIONS OBSERVED: Good Acceptable Poor

MAINTENANCE AND REPAIRS

- PROBLEMS NOTED** (60) NONE (61) ACCESS ROAD NEEDS MAINTENANCE (62) LIVESTOCK DAMAGE
 (63) BRUSH ON UPSTREAM SLOPE, CREST DOWNSTREAM SLOPE, TOE (64) TREES ON UPSTREAM SLOPE, CREST DOWNSTREAM SLOPE, TOE
 (65) RODENT ACTIVITY ON UPSTREAM SLOPE, CREST DOWNSTREAM SLOPE, TOE (66) DETERIORATED CONCRETE - FACING, OUTLET SPILLWAY
 (67) GATE AND OPERATING MECHANISM NEED MAINTENANCE (68) OTHER

Dam appears exceptionally well-maintained.

CONDITIONS OBSERVED: Good Acceptable Poor

Go to next page for Overall Conditions and Items Requiring Actions

OVERALL CONDITIONS

Embankment exhibits excellent seepage control and is very well-maintained. There are no immediate safety concerns.

Based on this Safety Inspection and recent file review, the overall condition is determined to be:

- (71) SATISFACTORY (72) CONDITIONALLY SATISFACTORY (73) UNSATISFACTORY

ITEMS REQUIRING ACTION BY OWNER TO IMPROVE THE SAFETY OF THE DAM

ENGINEERING - EMPLOY AN ENGINEER EXPERIENCED IN DESIGN AND CONSTRUCTION OF DAMS TO


- PERFORM AN INTERNAL INSPECTION OF THE OUTLET

7/26/2024 - I will contact you later this year to perform inspection with the State's pipe crawler.

The State Engineer, by providing this dam safety inspection report, does not assume responsibility for any unsafe condition of the subject dam. The sole responsibility for the safety of this dam rests with the reservoir owner or operator, who should take every step necessary to prevent damages caused by leakage or overflow of waters from the reservoir or floods resulting from a failure of the dam.

SAFE STORAGE LEVEL: RECOMMENDED AS A RESULT OF THIS INSPECTION

- (101) FULL STORAGE
 (102) CONDITIONAL FULL STORAGE
 (103) RECOMMENDED RESTRICTION
 (104) CONTINUE EXISTING RESTRICTION



REASON FOR RESTRICTION

ACTIONS REQUIRED FOR CONDITIONAL FULL STORAGE OR CONTINUED STORAGE AT THE RESTRICTED LEVEL:

Engineer's Signature: INSPECTED BY
 Owner's Signature: _____ OWNER/OWNER'S REPRESENTATIVE DATE: ____/____/____

GUIDELINES FOR DETERMINING CONDITIONS

CONDITIONS OBSERVED - APPLIES TO UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, OUTLET, SPILLWAY

GOOD In general, this part of the structure has a near new appearance, and conditions observed in this area do not appear to threaten the safety of the dam.	ACCEPTABLE Although general cross-section is maintained, surfaces may be irregular, eroded, rutted, spalled, or otherwise not in new condition. Conditions in this area do not currently appear to threaten the safety of the dam.	POOR Conditions observed in this area appear to threaten the safety of the dam.
--	--	---

CONDITIONS OBSERVED - APPLIES TO SEEPAGE

GOOD No evidence of uncontrolled seepage. No unexplained increase in flows from designed drains. All seepage is clear. Seepage conditions do not appear to threaten the safety of the dam.	ACCEPTABLE Some seepage exists at areas other than the drain outfalls, or other designed drains. No unexplained increase in seepage. All seepage is clear. Seepage conditions observed do not currently appear to threaten the safety of the dam.	POOR Seepage conditions observed appear to threaten the safety of the dam. Examples: 1) Designed drain or seepage flows have increased without increase in reservoir level. 2) Drain or seepage flows contain sediment, i.e., muddy water or particles in jar samples. 3) Widespread seepage, concentrated seepage, or ponding appears to threaten the safety of the dam.
--	---	--

CONDITIONS OBSERVED - APPLIES TO MONITORING

GOOD Monitoring includes movement surveys and leakage measurements for all dams, and piezometer readings for High hazard dams. Instrumentation is in reliable, working condition. A plan for monitoring the instrumentation and analyzing results by the owner's engineer is in effect. Periodic inspections by owner's engineer.	ACCEPTABLE Monitoring includes movement surveys and leakage measurements for High and Significant hazard dams; leakage measurements for Low hazard dams. Instrumentation is in serviceable condition. A plan for monitoring instrumentation is in effect by owner. Periodic inspections by owner or representative. OR, NO MONITORING REQUIRED.	POOR All instrumentation and monitoring described under "ACCEPTABLE" here for each class of dam, are not provided, or required periodic readings are not being made, or unexplained changes in readings are not reacted to by the owner.
---	---	--

CONDITIONS OBSERVED - APPLIES TO MAINTENANCE AND REPAIR

GOOD Dam appears to receive effective on-going maintenance and repair, and only a few minor items may need to be addressed.	ACCEPTABLE Dam appears to receive maintenance, but some maintenance items need to be addressed. No major repairs are required.	POOR Dam does not appear to receive adequate maintenance. One or more items needing maintenance or repair has begun to threaten the safety of the dam.
---	--	--

OVERALL CONDITIONS

SATISFACTORY The safety inspection indicates no conditions that appear to threaten the safety of the dam, and the dam is expected to perform satisfactorily under all design loading conditions. Most of the required monitoring is being performed.	CONDITIONALLY SATISFACTORY The safety inspection indicates symptoms of structural distress (seepage, evidence of minor displacements, etc.), which, if conditions worsen, could lead to the failure of the dam. Essential monitoring, inspection, and maintenance must be performed as a requirement for continued full storage in the reservoir.	UNSATISFACTORY The safety inspection indicates definite signs of structural distress (excessive seepage, cracks, slides, sinkholes, severe deterioration, etc.), which could lead to the failure of the dam if the reservoir is used to full capacity. The dam is judged unsafe for full storage of water.
--	---	--

SAFE STORAGE LEVEL

FULL STORAGE Dam may be used to full capacity with no conditions attached.	CONDITIONAL FULL STORAGE Dam may be used to full storage if certain monitoring, maintenance, or operational conditions are met.	RESTRICTION Dam may not be used to full capacity, but must be operated at some reduced level in the interest of public safety.
--	---	--

HAZARD CLASSIFICATION OF DAMS

High hazard Loss of human life is expected in the event of failure of the dam, while the reservoir is at the high water line.	Significant hazard Significant damage to improved property is expected in the event of failure of the dam while the reservoir is at the high water line, but no loss of human life is expected.	Low hazard Loss of human life is not expected, and damage to improved property is expected to be small, in the event of failure of the dam while the reservoir is at high water line.
---	---	---

NPH hazard - No loss of life or damage to improved property, or loss of downstream resource is expected in the event of failure of the dam while the reservoir is at the high water line.

Turner Dam

by Gavin, Matthew

August 26, 2024



Spillway Channel – Upstream End



Spillway Channel – Looking Downstream



Looking at Upstream Slope from Spillway



Vault in Spillway Channel



Flow Over Gate Inside Vault



Flume Vault



Flume Inside Vault



Staff Gage on Flume



Lid of Vault



Crest from Right End



Upstream Slope and Crest



Outlet Operator Vault



Outlet Operator



Crest from Left End



Upstream Slope from Left End



Left Groin and Downstream Slope



Outlet Outfall



Exercising Outlet